

IMPORTANT - PLEASE NOTE

Used with just the battery harness, this jacket will operate at maximum heat, which unless used in extremely cold climates (i.e Scandinavia), will be too hot and could cause skin discomfort unless disconnected. In order to adjust the temperature you will need a Gerbing temperature controller. To view available options, depending on your requirements, [please click here.](#)

SIZE GUIDE

The table below gives the actual measurements of each jacket size. Please note that the jackets have a compression fit, with wide stretch panels on the inside of the arms and at each side of the torso. Choose the size nearest to your measurements for maximum warmth and best fit. Experience has shown that most jacket exchanges occur because customers feel their jackets are too small. If in doubt, or if you prefer a slightly looser fit, order the next size UP.

JACKET SIZE	CHEST MEASUREMENT
XXS	34" (86cm)
XS	36" (91cm)
S	38" (97cm)
M	40" (102cm)
L	42" (107cm)
XL	44" (112cm)
XXL	46" (117cm)
XXXL	48" (122cm)